## Exhibit W



External Number FRM000710

Asset Mackenzie Rose Effective Date **12/01/2018** 

Document SEAR MISS REPORT Page 2 of 3 PageID#

Filled By Christopher (Chris) L. Miller Tags **Near Miss** 

Filled **02/28/2024 07:00** 

## Form Response Items

I	▲ ii Item	II Value	
1	9.2 Near Miss Report		No. of Street, or other Persons and Street, o
1.1	Near Miss subject	AUTO PILOT FAILURE	
1.2	Choose appropriate level for near miss:	Use Caution and Report	. and department of the same
1.3	Location:	UW TO NY	The second second
1.4	Reported by (Optional):	Christopher (Chris) L. Miller	And the second
1.5	Description of Near Miss:	AUTO PILOT STOPPED TUG TOOK A HARD LEFT INTO OTHERN TRAFFIC LANE.	
1.6	Actions Taken to Prevent Repeat of Incident:	BE VIGILANT WHILE STANDING WATCH, WATCH FOR SUDDEN HEADING CHANGES.	
2	Office Use ONLY	Approved on 03/04/2024 07:15	
2.1	Received date:	03/04/2024	
2.2	Received by:	Brian Moore	
2.3	Lessons learned created? (employee who is approving this near miss shoreside should also complete the Lessons Learned form-9.7- in correlation with this near miss).	No	Problems
2.4	Relevant section of TSMS:		
2.5	Remedial activities or training required:		
		CARVER 000037	rymarr.

2.6 Risk Severity Probability: